

# NI 9264 Calibration Procedure

This document contains information about calibrating National Instruments 9264 modules using NI-DAQmx. This calibration procedure is intended for metrology labs.

This document does not discuss programming techniques or compiler configuration. The NI-DAQmx driver contains online help files that have compiler-specific instructions and detailed function explanations. You can install these help files when you install NI-DAQmx on the calibration computer.

## Contents

---

Conventions .....	2
Software .....	2
Documentation .....	3
Calibration Interval .....	3
Test Equipment .....	4
Test Conditions .....	4
Calibration Procedure .....	4
Calibration Process Overview .....	4
Initial Setup .....	5
Verification Procedure .....	5
Specifications .....	9
Test Limits .....	9
Range .....	9
Test Point .....	9
1-Year Limits .....	9
Where to Go for Support.....	11

# Conventions

---

The following conventions appear in this manual:

» The » symbol leads you through nested menu items and dialog box options to a final action. The sequence **File»Page Setup»Options** directs you to pull down the **File** menu, select the **Page Setup** item, and select **Options** from the last dialog box.



This icon denotes a note, which alerts you to important information.

**bold** Bold text denotes items that you must select or click in the software, such as menu items and dialog box options. Bold text also denotes parameter names and hardware labels.

*italic* Italic text denotes variables, emphasis, a cross-reference, or an introduction to a key concept. Italic text also denotes text that is a placeholder for a word or value that you must supply.

monospace Monospace text denotes text or characters that you should enter from the keyboard, sections of code, programming examples, and syntax examples. This font is also used for the proper names of disk drives, paths, directories, programs, subprograms, subroutines, device names, functions, operations, variables, filenames, and extensions.

## Software

---

Install NI-DAQmx 8.6 or later on the calibration computer. NI-DAQmx includes high-level function calls to simplify the task of writing software to calibrate devices. You must have the proper device driver installed on the calibration system before calibrating the device.



**Note** NI recommends that you install the NI-DAQmx driver software before physically installing the NI 9264. NI-DAQmx, available at [ni.com/downloads](http://ni.com/downloads), configures and controls the NI 9264.

NI-DAQmx supports a number of programming languages, including LabVIEW, LabWindows™/CVI™, Microsoft Visual C++ 6.0, Microsoft Visual Basic 6.0, Microsoft .NET, and Borland C++.

You can access the NI-DAQmx header file, `NIDAQmx.h`, like any standard library. You can find examples of how to use the NI-DAQmx driver in the `Program Files\National Instruments\NI-DAQ\Examples` directory.

# Documentation

---

You might find the following documentation helpful as you write the calibration procedure:

- *NI-DAQmx Help*—This help file contains general information about measurement concepts, key NI-DAQmx concepts, and common applications that apply to all programming environments. To access this help file, select **Start»All Programs»National Instruments»NI-DAQ»NI-DAQmx Help**.
- *NI-DAQmx C Reference Help*—This help file contains C reference and general information about measurement concepts. To access this help file, select **Start»All Programs»National Instruments»NI-DAQ»NI-DAQmx C Reference Help**.
- *DAQ Getting Started Guide for NI-DAQ 8.0 or later*—This guide describes how to install NI-DAQmx for Windows software and NI-DAQmx-supported DAQ devices, and how to confirm that your device is operating properly. To access this guide, select **Start»All Programs»National Instruments»NI-DAQ»DAQ Getting Started Guide**.



**Note** The documents above are installed with NI-DAQmx. You can also download the latest versions from the NI Web site at [ni.com/manuals](http://ni.com/manuals).

- *NI 9264 Operating Instructions and Specifications*—This document describes how to use the NI 9264 and includes specifications and pin assignments for the NI 9264. The limits you use to verify the accuracy of this device are based on the specifications found in this document. You can download the latest version of this document from the NI Web site at [ni.com/manuals](http://ni.com/manuals).

## Calibration Interval

---

The NI 9264 should be calibrated at a regular interval as defined by the measurement accuracy requirements of your application. National Instruments recommends that you routinely perform a complete calibration at least once every year. You can shorten this interval based on the accuracy demands of your application or requirements of your processes.

# Test Equipment

---

National Instruments recommends that you use the following equipment for calibrating the NI 9264.

**Table 1.** Recommended Equipment

Equipment	Recommended Model	Requirements
DMM	NI 4070 DMM	If this instrument is unavailable, use a multiranging 6 1/2 digit DMM with an accuracy of 40 ppm.
Chassis	NI cDAQ-9172	—
Connection Accessory	NI 9974	—

## Test Conditions

---

Follow these guidelines to optimize the connections and the environment:

- Keep connections to the device as short as possible. Long cables and wires act as antennae, picking up extra noise that can affect measurements.
- Use shielded copper wire for all cable connections to the device. Use twisted-pair wire to eliminate noise and thermal offsets.
- Maintain an ambient temperature of  $23 \pm 10$  °C. The device temperature will be greater than the ambient temperature.
- Keep relative humidity below 80%.
- Allow a warm-up time of at least 10 minutes to ensure that the measurement circuitry is at a stable operating temperature.

## Calibration Procedure

---

This section provides instructions for verifying the performance of the NI 9264.

### Calibration Process Overview

The calibration process consists of the following steps:

1. *Initial Setup*—Configure the device in NI-DAQmx.
2. *Verification Procedure*—Verify the existing operation of the device. This step confirms whether the device was operating within its specified range prior to calibration.

3. **Adjustment**—If the device does not fall within the desired specifications, submit the device to NI for a factory calibration to adjust the calibration constants.
4. *Verification Procedure*— Perform another verification to ensure that the device operates within its specifications after adjustment.

The first two steps are explained in the following sections.

## Initial Setup

You must configure the device in Measurement & Automation Explorer (MAX) to communicate with NI-DAQmx.

Complete the following steps to configure a device in MAX:

1. Install the NI-DAQmx driver software.
2. Make sure that no power is connected to the module terminals. If the system is in a nonhazardous location, the chassis power can be on when you install the module.
3. Insert the module into an available slot in the cDAQ-9172 chassis.
4. Launch MAX.
5. Right-click the device name and select **Self-Test** to ensure that the device is working properly.




**Note** When a device is configured with MAX, it is assigned a device name. Each function call uses this device name to determine which DAQ device to calibrate. This document uses `dev1` to refer to the device name. In the following procedures, use the device name as it appears in MAX.

## Verification Procedure

Verification determines how well the device is meeting its specifications. By completing this procedure, you can see how the device has drifted over time, which helps you determine the appropriate calibration interval for your application. Table 3 in the *Test Limits* section shows all acceptable settings for the device type. Throughout the verification process, use Table 3 to determine if the device is operating within its specified range.

Complete the following steps to test the performance of the device:

1. Connect the positive output of the DMM to an AO terminal and the negative output of the DMM to a COM terminal. Refer to Figure 1 for the pin assignments of the NI 9264.



**Figure 1.** NI 9264 Pin Assignments

2. If you use C function calls, create a task using `DAQmxCreateTask`, as shown in the following table. If you use LabVIEW, skip this step. The task is created in step 3 in LabVIEW.

LabVIEW Block Diagram	NI-DAQmx Function Call
LabVIEW does not require this step.	Call <code>DAQmxCreateTask</code> with the following parameters: <b>taskName:</b> <code>AOVerificationTask</code> <b>taskHandle:</b> <code>&amp;taskHandle</code>


3. Create and configure an AO voltage channel using the DAQmx Create Virtual Channel VI, as shown in the following table. Use Table 3 to determine the minimum and maximum values for the device.




**Note** Throughout the procedure, refer to the NI-DAQmx function parameters for the LabVIEW input values. Refer to the block diagram images for the correct instance to use for polymorphic VIs.

LabVIEW Block Diagram	NI-DAQmx Function Call
	<p>Call  DAQmxCreateAOVoltageChan  with the following parameters:</p> <p><b>taskHandle:</b> taskHandle  <b>physicalChannels:</b> dev1/ao0  <b>nameToAssignToChannel:</b>  <i>myVoltageChannel</i>  <b>minVal:</b> -10.0  <b>maxVal:</b> 10.0  <b>units:</b> DAQmx_Val_Volts  <b>customScaleName:</b> NULL</p>

4. Generate the voltage output using the DAQmx Write VI, as shown in the following table.

LabVIEW Block Diagram	NI-DAQmx Function Call
 <p>The LabVIEW block diagram shows a DAQmx Write VI block. It has four input terminals on the left: 'task/channels in' (I/O), 'data' (DBI), 'timeout' (DBI), and 'error in' (E). The 'task/channels in' terminal is connected to a 'task out' terminal on the right (I/O). The 'data' terminal is connected to a 'data' terminal on the right (DBI). The 'timeout' terminal is connected to a 'timeout' terminal on the right (DBI). The 'error in' terminal is connected to an 'error out' terminal on the right (E). The DAQmx Write VI block is also connected to an 'Analog DBL 1Chan 1Samp' block. An 'auto start' control is connected to the DAQmx Write VI block.</p>	<p>Call DAQmxWriteAnalogF64 with the following parameters:</p> <p><b>taskHandle:</b> taskHandle  <b>numSampsPerChan:</b> 1  <b>autoStart:</b> 1  <b>timeout:</b> 10.0  <b>dataLayout:</b> DAQmx_Val_GroupByChannel  <b>writeArray:</b> &amp;data  <b>sampsPerChanWritten:</b> &amp;sampsWritten  <b>reserved:</b> NULL</p>

5. Wait 1 ms to ensure the output is settled.
6. Compare the resulting values that the DMM shows to the Upper Limit and Lower Limit values in Table 3. If the result is between these values, the device passes the test.
7. Clear the acquisition using the DAQmx Clear Task VI, as shown in the following table.

LabVIEW Block Diagram	NI-DAQmx Function Call
 <p>The LabVIEW block diagram shows a DAQmx Clear Task VI block. It has two input terminals on the left: 'task in' (I/O) and 'error in' (E). The 'task in' terminal is connected to a 'task out' terminal on the right (I/O). The 'error in' terminal is connected to an 'error out' terminal on the right (E).</p>	<p>Call DAQmxClearTask with the following parameter:</p> <p><b>taskHandle:</b> taskHandle</p>

8. Repeat steps 2 through 7 for all channels and all values.
9. Disconnect the DMM from the device.

# Specifications

---

The values in the following table are based on calibrated scaling coefficients, which are stored in the onboard EEPROM. The following calibration specifications are for  $23 \pm 10$  °C.

**Table 2.** NI 9264 Accuracy

<b>Percent of Reading (Gain Error)</b>	<b>Percent of Range* (Offset Error)</b>
0.05%	0.05%
* Range equals 10.5 V	

## Test Limits

---

Table 3 lists the specifications that the NI 9264 should meet if it has been one year between calibrations. The following definitions describe how to use the information from Table 3.

### Range

*Range* refers to the minimum or maximum voltage range of an output signal.

### Test Point

The *Test Point* is the voltage value that is input or output for verification purposes. This value is broken down into two columns—*Location* and *Value*. *Location* refers to where the test value fits within the test range. *Value* refers to the voltage value to be verified. *Max* refers to maximum value, *Min* refers to minimum value, and *Mid* refers to mid-scale.

### 1-Year Limits

The *1-Year Limits* column contains the *Upper Limits* and *Lower Limits* for the test point value. That is, when the device is within its 1-year calibration interval, the test point value should fall between these upper and lower limit values.

**Table 3.** NI 9264 Verification Test Limits

<b>Range (V)</b>		<b>Test Point</b>		<b>1-Year Limits</b>	
<b>Minimum</b>	<b>Maximum</b>	<b>Location</b>	<b>Value (V)</b>	<b>Lower Limit (V)</b>	<b>Upper Limit (V)</b>
-10.000	10.000	Max	9.500000	9.490000	9.510000
-10.000	10.000	Mid	0.000000	-0.005250	0.005250
-10.000	10.000	Min	-9.500000	-9.510000	-9.490000

# Where to Go for Support

---

The National Instruments Web site is your complete resource for technical support. At [ni.com/support](http://ni.com/support) you have access to everything from troubleshooting and application development self-help resources to email and phone assistance from NI Application Engineers.

National Instruments corporate headquarters is located at 11500 North Mopac Expressway, Austin, Texas, 78759-3504. National Instruments also has offices located around the world to help address your support needs. For telephone support in the United States, create your service request at [ni.com/support](http://ni.com/support) and follow the calling instructions or dial 512 795 8248. For telephone support outside the United States, contact your local branch office:

Australia 1800 300 800, Austria 43 662 457990-0,  
Belgium 32 (0) 2 757 0020, Brazil 55 11 3262 3599,  
Canada 800 433 3488, China 86 21 5050 9800,  
Czech Republic 420 224 235 774, Denmark 45 45 76 26 00,  
Finland 358 (0) 9 725 72511, France 01 57 66 24 24,  
Germany 49 89 7413130, India 91 80 41190000, Israel 972 3 6393737,  
Italy 39 02 41309277, Japan 0120-527196, Korea 82 02 3451 3400,  
Lebanon 961 (0) 1 33 28 28, Malaysia 1800 887710,  
Mexico 01 800 010 0793, Netherlands 31 (0) 348 433 466,  
New Zealand 0800 553 322, Norway 47 (0) 66 90 76 60,  
Poland 48 22 3390150, Portugal 351 210 311 210, Russia 7 495 783 6851,  
Singapore 1800 226 5886, Slovenia 386 3 425 42 00,  
South Africa 27 0 11 805 8197, Spain 34 91 640 0085,  
Sweden 46 (0) 8 587 895 00, Switzerland 41 56 2005151,  
Taiwan 886 02 2377 2222, Thailand 662 278 6777,  
Turkey 90 212 279 3031, United Kingdom 44 (0) 1635 523545

National Instruments, NI, ni.com, and LabVIEW are trademarks of National Instruments Corporation. Refer to the *Terms of Use* section on [ni.com/legal](http://ni.com/legal) for more information about National Instruments trademarks. Other product and company names mentioned herein are trademarks or trade names of their respective companies. For patents covering National Instruments products, refer to the appropriate location: **Help»Patents** in your software, the `patents.txt` file on your CD, or [ni.com/patents](http://ni.com/patents).