
NOTE TO USERS

NI USB-8452 Firmware Compatibility

The NI USB-8452 in this kit has been updated to a firmware version that is incompatible with NI-845x driver versions prior to 2.1. If an NI-845x driver version prior to 2.1 is installed on your system, you need to upgrade your driver by using the enclosed installation CD or downloading the latest NI-845x driver from ni.com/downloads.

If you cannot upgrade the NI-845x driver on your system, you can refer to an online document for additional options. Visit ni.com/info and enter the Info Code 8452FW.

LabVIEW, National Instruments, NI, ni.com, the National Instruments corporate logo, and the Eagle logo are trademarks of National Instruments Corporation. Refer to the *Trademark Information* at ni.com/trademarks for other National Instruments trademarks. Other product and company names mentioned herein are trademarks or trade names of their respective companies. For patents covering National Instruments products/technology, refer to the appropriate location: **Help»Patents** in your software, the `patents.txt` file on your media, or the *National Instruments Patent Notice* at ni.com/patents. You can find information about end-user license agreements (EULAs) and third-party legal notices in the NI-845x Readme. Refer to the *Export Compliance Information* at ni.com/legal/export-compliance for the National Instruments global trade compliance policy and how to obtain relevant HTS codes, ECCNs, and other import/export data.