

RELEASE NOTES

Calibration Executive

Version 3.1

Known Issues

This document explains how to address known issues in Calibration Executive 3.1 that affect the following National Instruments devices:

- M Series DAQ devices
- NI 6110/6111
- NI 4350/4351
- NI 6703/6704
- NI 4050/4060
- NI 6013/6014/6015/6016
- NI 6123

To address these issues, install both of the following updates from ni.com/downloads:

- Calibration Executive 3.1.1 Patch
- NI-DAQmx version 8.1

National Instruments, NI, ni.com, and LabVIEW are trademarks of National Instruments Corporation. Refer to the *Terms of Use* section on ni.com/legal for more information about National Instruments trademarks. Other product and company names mentioned herein are trademarks or trade names of their respective companies. For patents covering National Instruments products, refer to the appropriate location: **Help»Patents** in your software, the `patents.txt` file on your CD, or ni.com/patents.