

## NOTE TO USERS

# cRIO-906x and NI 9149

## Software Support

National Instruments has resolved an issue that affects the following devices:

- cRIO-9066
- cRIO-9067
- cRIO-9068
- NI 9149

National Instruments strongly recommends that you update all development systems that interact with cRIO-906x or NI 9149 devices to RIO Device Drivers August 2014 f1 or later. You can install this software using the DVD included in this shipping kit.

Visit [ni.com/info](http://ni.com/info) and enter the Info Code `rio2014f1` for more information about this update.



Refer to the *NI Trademarks and Logo Guidelines* at [ni.com/trademarks](http://ni.com/trademarks) for more information on National Instruments trademarks. Other product and company names mentioned herein are trademarks or trade names of their respective companies. For patents covering National Instruments products/technology, refer to the appropriate location: **Help»Patents** in your software, the `patents.txt` file on your media, or the *National Instruments Patent Notice* at [ni.com/patents](http://ni.com/patents). You can find information about end-user license agreements (EULAs) and third-party legal notices in the `readme` file for your NI product. Refer to the *Export Compliance Information* at [ni.com/legal/export-compliance](http://ni.com/legal/export-compliance) for the National Instruments global trade compliance policy and how to obtain relevant HTS codes, ECCNs, and other import/export data. NI MAKES NO EXPRESS OR IMPLIED WARRANTIES AS TO THE ACCURACY OF THE INFORMATION CONTAINED HEREIN AND SHALL NOT BE LIABLE FOR ANY ERRORS. U.S. Government Customers: The data contained in this manual was developed at private expense and is subject to the applicable limited rights and restricted data rights as set forth in FAR 52.227-14, DFAR 252.227-7014, and DFAR 252.227-7015.

© 2014 National Instruments. All rights reserved.  
Printed in Hungary.

326312A-01

Aug14

