

NOTE TO USERS

NI WSN-9791

The NI WSN-9791 ships with firmware that is compatible with NI LabVIEW 2010. To use this device with NI LabVIEW 2009 SP1 or earlier, complete the following steps:

1. Install NI-WSN 1.2 or later.
2. Connect the NI WSN-9791 to the network or directly connect it to your computer.
3. Open Measurement and Automation Explorer (MAX), and expand **Remote Systems**.
4. Select the NI WSN-9791.
5. Select the **Gateway Firmware** tab and then click **Browse**.
6. Select the file named `ni9791fwROM_LV861_LV2009.cfg`, and click **OK**.
7. Click **Update Firmware**.



LabVIEW, National Instruments, NI, ni.com, the National Instruments corporate logo, and the Eagle logo are trademarks of National Instruments Corporation. Refer to the *Trademark Information* at ni.com/trademarks for other National Instruments trademarks. Other product and company names mentioned herein are trademarks or trade names of their respective companies. For patents covering National Instruments products/technology, refer to the appropriate location: **Help»Patents** in your software, the `patents.txt` file on your media, or the *National Instruments Patent Notice* at ni.com/patents.

© 2010 National Instruments Corp. All rights reserved.